

VD2

AUXILIARY BOARD

- SOLID-STATE DESIGN
- (2) I/Os w/ PRIORITY SENSING
- Euro style connectors
- 3-Year Warranty









Solutions to Make Your Life Easier

When Von Duprin discontinued the PS873 power supply and the add-on boards associated with that power supply. Command Access developed a replacement board manufactured with similar characteristics to PS871-2 board. The new **VD2-872** board mounts to the PS873 in the same fashion as the factory original PS871-2 board.

After the success of the VD2-873, we developed the **VD2-914** replacement relay board that fits and functions just the same as the original factory 2RS board for the Von Duprin PS914, with the added addition of a .5A power tap. Whether it be old or new style, we got you covered!

How to Order

PART #	ASY ORDER	# DESCRIPTION
VD2-873	70817	PS873 replacement relay board.
VD2-914	79616	PS914 replacement relay board.